Oil Field Environmental Incident Summary

Incident: 20170603200439 Date/Time of Notice: 06/03/2017 20:04

Responsible Party: Bridger Pipeline LLC

BURLINGTON RESOURCES OIL & GAS COMPANY LP Well Operator:

Well Name: BIG BEND 41-2TFH CTB

Field Name: CAMEL BUTTE Well File #:

Date Incident: 6/2/2017 Time Incident: 19:35 Facility ID Number: 226089-01 County: **MCKENZIE Twp:** 151 **Sec:** 2 Qtr: LO 1 **Rng:** 96

Location Description: East side of the pad extending approximately 279 feet.

Submitted By: Lewis Schoenberger Received By:

Contact Person: Lewis Schoenberger

600 N. DAIRY ASHFORD HOUSTON, TX 77079

General Land Use: Well/Facility Site Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: No

> **Units** Spilled Recovered Units **Followup Units** 160 barrels

Oil 144 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/6/2017 Clean Up Concluded: 6/19/2017

Risk Evaluation:

None.

Areal Extent:

Approximately 75 feet by 240 feet.

Potential Environmental Impacts:

None. The spill was contained in the vicinity of the facility pad by construction of a temporary earthen dike.

Page 1 of 3

Action Taken or Planned:

Wastes Disposal Location: The oil will be collected and placed into a tank for sale. The impacted soil and vegetation will be collected for appropriate disposal,

Agencies Involved:

Updates

Date: 6/5/2017 Status: Inspection Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Inspection Date: 6/5/2017

Arrived at 1645. I met with the crew leader on site and he showed me the extent of the release. He told me that their environmental team will be out Wednesday to take confirmation soil samples before they backfill.

The release occurred from a broken gasket near the north edge of the pad. The release ran along the north edge of the pad, flowed through the access road culvert and went east along the ditch. The excavation on the east was about 3' deep, 8' wide and ran almost the entire length of the pad. The excavation to the north was still underway. Earthen berms were placed inside the excavated areas near the culverts. Photos were taken and can be found in the report folder. Further follow-up is needed on the progress of the clean up.

Date: 6/5/2017 Status: Reviewed - Follow-up Required Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Called responsible party representative on June 3, 2017, who said that approximately 120 barrels of crude oil have already been hydrovaced. The release went 450 feet east off the well pad. An excavator is on site and there is a berm in place. Further follow-up is needed.

Date: 7/25/2017 Status: Inspection Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 14:20. 83 degrees F, Sunny, NW wind 15-25 mph. Observed the site and took photos. It appeared that the release exited the well pad along the west side of the entrance road and flowed east through a culvert approximately 150 feet, then followed the county road to the south for approximately 400 feet. It then flowed east again through a culvert to the road ditch. Soils had been brought in, graded, landscaped, but not seeded. Further follow-up needed. Photos added to incident folder.